



- ① - Restripe crosswalk on Rincon Avenue as ladder style .  
 - Install Assembly B signs at the crosswalk and Assembly D signs 100 feet in advance of the crosswalk (Existing crosswalk warning sign on southbound Rincon Avenue needs an "AHEAD" plaque.)  
 - Consider installing pedestrian actuated flashing beacons on Assembly B signs.  
 - Construct a curb extension into Rincon Avenue on the northwest corner of the intersection.  
 - Construct curb ramp at the east end of the crosswalk.
- ② - Install speed feedback sign on southbound Rincon Avenue approximately 200 feet north of Ora Avenue.
- ③ - Stripe white transverse crosswalk across Ora Avenue at Rincon Avenue.
- ④ - Install NO PARKING sign at leading end of existing red curb on north side of Marilyn Avenue at loading zone exit.
- ⑤ - Construct curb extension at north end of crosswalk on Marilyn Avenue.  
 - Paint an additional 10 feet of red curb on north side of Marilyn Avenue in advance of crosswalk at Albatross Avenue.  
 - Paint 20 feet of red curb on the southwest corner (Marilyn Avenue leg).  
 - Restripe crosswalk on Marilyn Avenue and Albatross Avenue as ladder style.  
 - Install Assembly B signage at each crosswalk and install Assembly D signage on westbound Marilyn Avenue approximately 300 feet in advance of Albatross Avenue (standard installation distance of 100 feet conflicts with recommended NO PARKING sign).
- ⑥ - Paint yellow ladder crosswalks across Falcon Way and Marilyn Avenue.  
 - Construct curb ramps at the ends of each crosswalk.  
 - Install Assembly B signage at each crosswalk and install Assembly D signage on Falcon Way 100 feet in advance of Marilyn Avenue.  
 - Paint SLOW SCHOOL XING in advance of Falcon Way crosswalk.
- ⑦ - Construct curb extensions into Olivina Avenue on the northeast and southeast corners of the intersection.  
 - Restripe crosswalk on east leg as ladder style.  
 - Install Assembly B signage at the crosswalk and Assembly D signage 100 feet in advance of the crosswalk.  
 - Paint 20 feet of red curb on north side of Olivina Avenue in advance of Albatross Avenue.
- ⑧ - Install speed feedback signs on Olivina Avenue approximately 400 in advance of Albatross Avenue. (Short Term: Request speed feedback trailer from the police department)

Assembly D	Assembly B	Assembly B & Flashing Beacon	Speed Feedback Sign	No Parking Sign	Slow School Crossing Marking

Alameda Safe Routes to School Partnership  
 Marilyn Avenue Elementary School, Livermore, CA  
 2/25/11